



GARY R. HERBERT
Governor
GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director
JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program June 26, 2013

Reviewed: PPM

Mine Name: Weston #1	Permit Number: S/007/0039
Operator Name: Quality Building Stone	Inspection Date: April 4, 2012
Inspector(s): Wayne Western	Time: 6:15- 6:30 pm
Other Participants: none	Mine Status: ACT
Weather Condition: clear skies and hot	Last Inspection: April 4, 2012
Bond Renewal Date: April 4, 2012	Bond Amount: April 4, 2012
Surface Ownership: Fee	Mineral Ownership: Fee
Last Year of Production: 2011 reported	Acreage: 3 acres permitted

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Bond/Bond Release	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Annual Fees	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Annual Report	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The Operator has a valid permit for the site. The annual permit fees have been paid. The annual report for 2012 was not received by the Division and the bond was due for renewal in 2010. The Division is working with the Operator to rectify the bond amount and escalation.

The site was inactive.

The main concerns with the site are the steep road cuts and how they will be reclaimed.

Conclusions and Recommendations:

The Division should work with the Operator to get the annual report for 2012 and get the bond escalated.

Directions to Site:

The site is west of Helper Utah. Location on topo accurate.

Inspector's Signature _____

WHW:

cc: (OPERATOR)

agencies

O:\M007-Carbon\S0070039-Weston1\inspections\Insp-06352013.doc



Looking east, notice steep road cut.



Close up of road cut.



Looking south at road cuts.



Entrance to mine